

25X1

CONFIDENTIAL

SECURITY INFORMATION

REPORT

25X1

COUNTRY Poland

DATE DISTR. *23 Oct 53,*

SUBJECT Mlociny Airfield

NO. OF PAGES 2

PLACE
ACQUIREDNO. OF ENCLS.
(LISTED BELOW)DATE
ACQUIRED BSUPPLEMENT TO
REPORT NO.

25X1

DATE OF INF

THIS IS UNEVALUATED INFORMATION

25X1

Mlociny Airfield N 52-18. E 20-567: Reference to Encl. #1, Overlay of
Location of Mlociny Airfield.

25X1

this was a Polish Military airfield. This airfield had
three reinforced concrete hangars on the East, West and South sides.
Hangars on East and West side of airfield were 120 x 30 x 15 m. and
hangars on South side were 80 x 30 x 15 m. There were two large con-
crete areas running North to South which were separated by a large
grassy area believed to be runways and estimated at 1,500
m. x 50 m. The Southwest corner of airfield had a three-story brick
building, 25 x 8 m. believed this to be a barrack. Entire air-
field was surrounded by a heavy forest, no fence was observed around
airfield.

25X1

25X1

25X1

some aircraft parked in front of hangars.

some were two engine
conventional type bombers, single engine jet fighters and biplanes

USAF review completed.

CONFIDENTIAL

SECURITY INFORMATION

25 YEAR RE-REVIEW

25X1

Page Denied

CONFIDENTIAL

25X1

-2-


Enclosure No. 1,

25X1

Overlay

Pinpointing Mlociny Airfield.

25X1



CONFIDENTIAL

25X1

Page Denied